	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comment s
1	BRS	L1	1819	wind near3 (mill turbine generator)	USPA T	2003/06/0 2 15:35	
2	BRS	L2	0	staor with magnet	USPA T	2003/06/0 2 15:35	
3	BRS	L3	8940	stator with magnet	USPA T	2003/06/0 2 16:04	
4	BRS	L4	10446 55	illuminat\$4 light beacon alarm sound	USPA T	2003/06/0 2 16:04	
5	BRS	L5	49	1 and 3	USPA T	2003/06/0 2 15:38	
6	BRS	L6	28	5 and 4	USPA T	2003/06/0 2 15:56	
7	BRS	L7	21	5 not 6	USPA T	2003/06/0 2 15:56	
8	BRS	L8	7566	stator with magnet	DERW ENT	2003/06/0 2 16:49	
9	BRS	L9		illuminat\$4 light beacon alarm sound	DERW ENT	2003/06/0 2 16:50	
10	BRS	L10	294	8 and 9	DERW ENT	2003/06/0 2 16:50	
11	BRS	L11	1271	stator with magnet	EPO	2003/06/0 2 16:51	
12	BRS	L12	0	10 and 11	USPA T	2003/06/0 2 16:49	
13	BRS	L13	0	10 and 11	EPO	2003/06/0 2 16:49	
14	BRS	L14		illuminat\$4 light beacon alarm sound	JPO	2003/06/0 2 16:50	
15	BRS	L15	5836	stator with magnet	JPO	2003/06/0 2 16:51	
16	BRS	L16	233	14 and 15	JPO	2003/06/0 2 16:51	
17	BRS	L17	6	16 and wind	JPO	2003/06/0 2 16:53	
18	BRS	L18	227	16 not 17	JPO	2003/06/0 2 16:53	